



CSA TECHNICAL INTERPRETATION REQUEST

DATE OF INQUIRY:

October 29, 2015

INTERPRETATION
NUMBER

15-01

PERTINENT CSA STANDARD(S):

CSA A440S1-09

SECTION(S) IN QUESTION:

CSA A440S1-09:
Clause 5.4 Water Penetration Resistance Test

INTERPRETATION REQUESTED:

1) Under CSA A440S1-09, at the end of a water penetration test performed on an outswing door in accordance with NAFS, is the presence of retained water on top of the interior sill weatherstrip but not penetrating the innermost plane of the product, or that subsequently flows onto the top of the exterior side of the sill when the door is opened, considered a failure?

SUGGESTED INTERPRETATION:

1) No.

REVIEWED/ APPROVED BY:

COMMITTEE	COMMENTS / ACTION	STATUS	DATE
CSA		Approved	Nov.2, 2015